

FIM2210-HV



NITGEN®

Stand-Alone Fingerprint Recognition Device (FIM2210-HV)

Change Report

(FIM2210-HV Ver. 1.91)

Version 1.91

© Copyright 2010 NITGEN Co., Ltd.

ALL RIGHTS RESERVED

Serial Number:

Specifications can be changed without notice.



Contents

- **FIRMWARE CHANGES FROM V1.90 TO V1.91.....4**
 - BUG FIXED - CHANGE TCS1CM INITIALIZATION ROUTINE.....4
- APPENDIX SUPPORT INFORMATION.....5**

FIM2210-HV

■ Firmware Changes from V1.90 to V1.91

Bug Fixed - Change TCS1CM Initialization Routine

When initialization failed, Time-Out error was appeared promptly in certain functions such as “Get Template”, “Verification” and “Identification”.

To address this phenomenon, Sensor Initialization Routine is modified.

Appendix Support Information

NITGEN&COMPANY CO., LTD.

12F PaxTower Nonhyun-dong, Gangnam-gu,
Seoul, 135-010 Korea
Tel: + 82-2-556-7115
Fax: + 82-2-556-7118
E-mail: Customer@nitgen.com